

DRILL LOG

PROJECT	남악시돌체 오룡지구 택지개발사		HOLE No.	TB(오룡)-6		REMARKS
CONTRACTOR	1111		COORDINATION	N : 21313 E : 13132		○ U.D.SAMPLE
LOCATION	1231312		ELEVATION	123.00 M		◎ S.P.T. SAMPLE
DATE	2012.2.22 ~ 2012.2.22		GROUND WATER	(GL-) 1231.00 M		● CORE SAMPLE
						⊗ DISTURBED SAMPLE

Scale m	ELEV. m	Depth m	Thick- ness m	Field Record				Standard Penetration Test and Field Vane Test					Sample							
				Graphic Log	Soil /Rock Type	Color	Description	N value / (blow/cm)	Blows			FVT kPa	N blow/Su(FVT)			No.	Depth	Type		
									15	15	15		20	40	60				80	100
0				● ●	표토층 SM	암갈색	□ 표토층(0.0~0.8m) 자갈섞인 실트질 모래													
1	122.20	0.80	0.80	● ●	풍화토 SM	암갈색	□ 풍화토(0.8~1.5m) 실트질 모래	100/30	18		28					S-1	1.0	◎		
2	121.50	1.50	0.70	● ●	보통암 WR	회색	□ 보통암(1.5~4.0m) 조밀 TCR: 74% RQD: 46%	100/30	18		28					S-2	2.5	◎		
3				+																
4	119.00	4.00	2.50	+																
5				+	경암 WR	회색	□ 경암(4.0~8.0m) TCR: 98% RQD: 98%													
6				+																
7				+																
8	115.00	8.00	4.00	+																
9	폰트 -1 만 줄여주세요						* 심도 8.00 M 에서 시추종료													
10																				
11																				
12																				
13																				
14																				
15																				
16																				
17																				
18																				
19																				
20																				

폰트 -1 만 줄여주세요

옆으로 옮겨주세요

예비타를 넣고싶은데 가능한지?

100이 이하를 넣어야 가능하도록 부탁드립니다.

심도별 베인결과를 넣고싶은데 가능한지?

없어졌음